

RESOLUTION NO. 2008-39

AUTHORIZING CONTRACT NO. 2007-129 WITH TRUCK TRAILER TRANSIT FOR THE FURNISHING OF BRAKE MAINTENANCE KITS, AS SPECIFIED AND AS REQUIRED, FOR A PERIOD OF ONE (1) YEAR IN AN AMOUNT NOT TO EXCEED \$231,590.00 (GENERAL FUND, FLEET MANAGEMENT DEPARTMENT BUDGET)

WHEREAS, the Greater Cleveland Regional Transit Authority has a need to perform brake maintenance as a normal part of the vehicle's scheduled maintenance on the 2100, 2200, 2500, 2600, 2800 and 9900 series coaches; and

WHEREAS, Section 306.43(H)(2) of the Ohio Revised Code provides that competitive bidding is not required when a regional transit authority, after reasonable inquiry, determines that only one source of supply is reasonably available; and

WHEREAS, the offer of Truck Trailer Transit, located at 1601 Theodore, Detroit, MI 48211, for the furnishing of brake maintenance kits, as specified and as required, was received on February 22, 2008; and

WHEREAS, after negotiations, Truck Trailer Transit agreed to furnish brake maintenance kits, as specified and as required, for a period of one (1) year in an amount not to exceed \$231,590.00; and

WHEREAS, the General Manager/Secretary-Treasurer deems the offer of Truck Trailer Transit as negotiated, to be fair and reasonable and recommends acceptance thereof by the Board of Trustees.

NOW, THEREFORE, BE IT RESOLVED by the Board of Trustees of the Greater Cleveland Regional Transit Authority, Cuyahoga County, Ohio:

Section 1. That the offer of Truck Trailer Transit, as negotiated, for the furnishing of brake maintenance kits, as specified and as required, for a period of one (1) year be and the same is hereby accepted.

Section 2. That the General Manager/Secretary-Treasurer of the Authority be and he is hereby authorized to enter into a sole source contract with Truck Trailer Transit, for the furnishing of brake maintenance kits, as specified and as required, for a period of one (1) year.


Section 3. That said contract shall be payable from the General Fund, Fleet Management Department budget, in an amount not to exceed two hundred thirty-one thousand five hundred ninety & 00/100 dollars (\$231,590.00).

Section 4. That said contract shall be binding upon and an obligation of the Authority contingent upon compliance by the contractor to the Specifications and Addenda; if any, the Affirmative Action Plan adopted by the Board of Trustees in Resolution 2007-064; bonding and insurance requirements and all applicable laws relating to contractual obligations of the Authority.

Section 5. That the Greater Cleveland Regional Transit Authority's Board of Trustees expects that Truck Trailer Transit will attempt to exceed the 0% minimum DBE goal assigned to this procurement.


Section 6. That this resolution shall become effective immediately upon its adoption.

Adopted: March 18, 2008



President

Attest:



CEO, General Manager/Secretary-Treasurer



Greater Cleveland Regional Transit Authority
STAFF SUMMARY AND COMMENTS

TITLE/DESCRIPTION: AUTHORIZING CONTRACT NO. 2007-129 WITH TRUCK TRAILER TRANSIT FOR THE FURNISHING OF BRAKE MAINTENANCE KITS, AS SPECIFIED AND AS REQUIRED, FOR A PERIOD OF ONE (1) YEAR IN AN AMOUNT NOT TO EXCEED \$231,590.00 (GENERAL FUND, FLEET MANAGEMENT DEPARTMENT BUDGET)	Resolution No.: 2008-39
	Date: March 13, 2008
	Initiator: Fleet Management Department
ACTION REQUEST: <input checked="" type="checkbox"/> Approval <input type="checkbox"/> Review/Comment <input type="checkbox"/> Information Only <input type="checkbox"/> Other _____	

1.0 **PURPOSE/SCOPE:** This action will allow the Authority to enter into a requirements contract with Truck Trailer Transit for the furnishing of brake maintenance kits for the Authority's 2100, 2200, 2500, 2600, 2800 and 9900 series coaches.

2.0 **DESCRIPTION/JUSTIFICATION:** The Authority has a requirement for the furnishing of brake maintenance kits on its NABI and Nova bus fleets. This procurement consists of four (4) different kits comprised of those components replaced regularly during normal brake maintenance.

3.0 **PROCUREMENT BACKGROUND:** Section 306.43 (H)(2) of the Ohio Revised Code allows for award of a sole source contract based upon a determination by the Board of Trustees, an officer or an employee of the Authority that there is only one source reasonably available for these items. Truck Trailer Transit presently is the only source qualified to provide these maintenance repair kits. The Authority will purchase four separate kits; a quantity of 200 each of the 80-22125 and the 85-22125 and a quantity of 120 each of the 85-26125 and the 85-39125.

A price analysis was performed and the Procurement Department has determined the negotiated offer of Truck Trailer Transit to be fair and reasonable to the Authority.

4.0 **AFFIRMATIVE ACTION/DBE BACKGROUND:** All Affirmative Action requirements have been met. A 0% DBE Goal was established for this procurement due to the lack of Certified DBE Firms.

5.0 **POLICY IMPACT:** Does not apply.

6.0 **ECONOMIC IMPACT:** This procurement will be funded through the General Fund, Fleet Management Department budget, in an amount not to exceed two hundred thirty-one thousand five hundred ninety & 00/100 dollars (\$231,590.00) for a period of one (1) year. The negotiated price is 3.5% below the budget estimate.

7.0 **ALTERNATIVES:** Reject this offer. Rejection of this offer would effect the quality of services provided for ridership and could also effect the safety of the vehicle.

8.0 RECOMMENDATION: It is recommended that the offer of Truck Trailer Transit be accepted and the resolution passed authorizing the General Manager/Secretary-Treasurer to enter into a contract.

9.0 ATTACHMENTS: Brake Maintenance Parts List

Recommended and certified as appropriate to the availability of funds, legal form and conformance with the Procurement requirements.



CEO, General Manager/Secretary-Treasurer

BRAKE MAINTENANCE PARTS LIST

NABI 2200-2500,2600/2800 & NOVA LFS 9900/2200 Front Axle (RTA # 80-22125 Complete)

<u>RTA #</u>	<u>Meritor No.</u>	<u>Qty</u>	<u>Description</u>
80-39015	2258-Y-1273	2	Spring Return
80-15133	1225-R-512	4	Bushing Cam
80-39005B	A-1205-V-1556	4	Seal Cam
80-39005A	1225-U-827	4	Bushing, Anchor Pin
80-39110J	1229-B-1848	8	Washer, Flat
80-39110K	1229-D-2942	10	Snap Ring, Anchor Pin
80-39110G	1259-B-1181	4	Anchor Pin
80-39110H	26-X-1030	4	Set Screw
75-00363	1199-N-1860	4	Grease Fitting
80-39014	CR 43764	*2	Seal - Inner
80-23015	2208-Z-390	2	Gasket
80-39104B	1229-H-4090	6	Washer Flat Spacer
80-39104C	4L-4-120/T-3651 (TTT)	8	Washer Spacing 1.265" ID, cam
80-39104D	1229-W-3117	10	Washer flat spacing
85-39104A	1229-E-4685	2	Special Washer
86-23150F	9003001P (MGM)	2	Carriage bolts
40-00414	T-25CP	2	Cotter Pin, 1/8" x 1 1/4"
86-12215	MR#36057 (Muncie)	2	Yoke Front
81-00063	4TA-3-4 (MCI)	2	Clevis Pin Front
86-22152	T-0024LS (TTT)	2	Diaphragms Front
86-39200	300-10041 / T-14637-ECAZ(TTT)	1	Slack Adjuster left Frt.
86-39201	300-10042 / T-14638-ECAZ(TTT)	1	Slack Adjuster Right Frt.
80-39002	2210-Z-8398	1	S-Cam Left Frt.
80-39003	2210-Y-8397	1	S-Cam Right Frt.

NABI 2200 – 2500 Rear Axle RTA # 85-22125 (Complete)

<u>RTA #</u>	<u>Meritor No.</u>	<u>Qty</u>	<u>Description</u>
80-39015	2258-Y-1273	2	Spring Return
80-39005A	1225-U-827	4	Bushing, Anchor Pin
80-39110J	1229-B-1848	8	Washer, Flat
80-39110K	1229-D-2942	8	Snap Ring, Anchor Pin
80-39110G	1259-B-1181	4	Anchor Pin
80-39110H	26-X-1030	4	Set Screw
80-39005B	A-1205-V-1556	4	Seal Cam
85-15133	1225-R-512	4	Bushing-Cam
75-00363	1199-N-1860	4	Grease Fitting
85-22014	CR-48693	**2	Seal – Inner
85-22015	CR-31390	***2	Seal Kit Hub outer
85-15085	2302132	2	Gasket Inner bearing
85-39104A	1229-E-4685	2	Special Washer
40-00414	T-25CP	2	Cotter Pin 1/8" x 1 1/4"

NABI 2200 – 2500 (Cont)
Rear Axle RTA # 85-22125 (Complete)

<u>RTA #</u>	<u>Meritor No.</u>	<u>Qty</u>	<u>Description</u>
86-22157	1245-D-186 (Meritor)	2	Yoke Rear
86-22157A	675330551 (Haldex)	2	Clevis Pin Rear
85-15082	CR-84343	2	Wiper
80-39104B	1229-H-4090	4	Washer Cam
80-39104C	4L-4-120 / T-3651 (TTT)	4	Washer Cam
80-39104D	1229-W-3117 / T-7113	6	Washer Cam
86-22203	41910880 / T-14664-ECAZ	1	Slack Adjuster Left Rear
86-22204	300-10159 / T-14663-ECAZ	1 ea.	Slack Adjuster Right Rear
85-22104	2210-H-8666 (Meritor)	1	S-Cam Left Rear
85-22103	2210-G-8665 (Meritor)	1	S-Cam Right Rear
95-22026	1229-G-4635 (Meritor)	2	Ring Lock Washer

NABI 2600/2800 (NEW KIT)
Rear Axle RTA # 85-26125 (Complete)

<u>RTA #</u>	<u>Meritor No.</u>	<u>Qty</u>	<u>Description</u>
80-39015	2258-Y-1273	2	Spring Return
80-39005A	1225-U-827	4	Bushing, Anchor Pin
80-39110J	1229-B-1848	8	Washer, Flat
80-39110K	1229-D-2942	8	Snap Ring, Anchor Pin
80-39110G	1259-B-1181	4	Anchor Pin
80-39110H	26-X-1030	4	Set Screw
80-39005B	A-1205-V-1556	4	Seal Cam
85-15133	1225-R-512	4	Bushing-Cam
80-15133	1199-N-1860	4	Grease Fitting
85-22014	CR-48693	**2	Seal - Inner
85-22015	CR-31390	***2	Seal Kit Hub outer
85-15085	2302132	2	Gasket Inner bearing
85-39104A	1229-E-4685	2	Special Washer
40-00414	T-25CP	2	Cotter Pin 1/8" x 1 1/4"
86-12215	1245-D-186 (Meritor)	2	Yoke Rear
86-22157A	675330551 (Haldex)	2	Clevis Pin Rear
85-15082	CR-84343	2	Wiper
80-39104B	1229-H-4090	4	Washer Cam
80-39104C	4L-4-120 / T-3651 (TTT)	4	Washer Cam
80-39104D	1229-W-3117 / T-7113	6	Washer Cam
86-26204	300-10045 / T-14639- ECAZ	2	Slack Adjuster Right & Left Rear
85-26104	2210-F-8690 (Meritor)	1	S-Cam Left Rear
85-26103	2210-E-8689 (Meritor)	1	S-Cam Right Rear
95-22026	1229G4635 (Meritor)	2	Ring Lock Washer

**NOVA LFS 9900/2100
Rear Axle RTA # 85-39125 (Complete)**

<u>RTA #</u>	<u>Meritor No.</u>	<u>Qty</u>	<u>Description</u>
80-39015	2258-Y-1273	2	Spring Return
80-39005A	1225-U-827	4	Bushing, Anchor Pin
80-39110J	1229-B-1848	8	Washer, Flat
80-39110K	1229-D-2942	10	Snap Ring, Anchor Pin
80-39110G	1259-B-1181	4	Anchor Pin

**NOVA LFS 9900/2100
Rear Axle RTA # 85-39125 (Complete) CONTINUED**

<u>RTA #</u>	<u>Meritor No.</u>	<u>Qty</u>	<u>Description</u>
80-39110H	26-X-1030	4	Set Screw
80-39005B	A-1205-V-1556	4	Seal Cam
85-15133	1225-R-512	4	Bushing-Cam
80-15133	1199-N-1860	4	Grease Fitting
85-39014	A-1205-V-2492	2	Seal - Inner
85-39015	2208-E-1123	2	Gasket Outer Hub
85-39104A	1229-E-4685	2	Special Washer
40-00414	T-25CP	2	Cotter Pin 1/8" x 1 1/4"
86-12215	1245-D-186 (Meritor)	2	Yoke Rear
81-00063	675330551 (Haldex)	2	Clevis Pin Rear
80-39104B	1229-H-4090	4	Washer Cam
80-39104C	4L-4-120 / T-3651 (TTT)	4	Washer Cam
80-39104D	1229-W-3117 / T-7113 (TTT)	6	Washer Cam
86-39203	419-79209 / T-14854-HZZZ	1	Slack Adjuster Left Rear
86-39204	419-79208 / T-14853-HZZZ	1	Slack Adjuster Right Rear
85-39104	2210-B-8140	1	S-Cam Left Rear
85-39105	2210-A-8139	1	S-Cam Right Rear
95-22026	1229G4635 (Meritor)	2	Ring Lock Washer